




NOTES:

1. Material- STKM11A-EC
2. Finish- NA
3. Material mechanical properties shall meet drawing
4. No burrs or sharp edges allowed.
5. Remove all burrs after machining.
6. Break all sharp edges.
7. Component shall be free from oil contamination, loose particles, and dust.
8. 100% inspection for the finished part.
9. All Dimension mentioned in drawing are of finished part.

SECTION A-A

