








SECTION A-A



NOTES:

1. Material- SAE1018
2. Finish- NA
3. Material mechanical properties shall meet drawing
- 4.No burrs or sharp edges allowed.
- 5.Remove all burrs after machining.
- 6.Break all sharp edges.
- 7.Component shall be free from oil contamination, loose particles, and dust.
- 8.100% inspection for bore diameter and length.
- 9.All Dimesnion mentioned in drawing are of finished part.