





SECTION A-A



NOTES:

1. Material- STKM11A-EC
2. Finish- NA
3. Material mechanical properties shall meet drawing
4. No burrs or sharp edges allowed.
5. Remove all burrs after machining.
6. Break all sharp edges.
7. Component shall be free from oil contamination, loose particles, and dust.
8. 100% inspection of the finished part.
9. All Dimesnion mentioned in drawing are of finished part.